

Aesculight

Packaging Instructions

No Notch in Foam



Step #1: Position Bottom Foam
(Note: No Notch in Bottom Foam)



Step #2: Lift Laser System into Box

Notched Foam

Footswitch



Step #3: Position Top Foam & Footswitch
(Note: Position of Notched Foam)



Step #4: Load Accessories & Tape Closed
(Note: Place Mast in Protective Pouch)



Step #5: Place Accessories Box Into Foam Cutouts
Step #6: Close Box and Seal All Edges with Packing Tape